



**RE: Kach Machine Works**

**Scheffler, Linda** to: Sanders, Dawn, Kristine Koch

10/04/2007 12:47 PM

We have not collected any inline data for that basin. Both ECSI sites in the basin are inactive, but the investigation at the AutoVending site (#1430) did identify TPH in soil.

-----Original Message-----

From: Sanders, Dawn  
Sent: Thursday, October 04, 2007 10:54 AM  
To: 'Koch.Kristine@epamail.epa.gov '  
Cc: Scheffler, Linda  
Subject: RE: Kach Machine Works

All our inriver data has been incorporated into the LWG's database so no, nothing in addition. I don't think we have any inline data either for this outfall but am copying Linda in case she thinks of something else.

-----Original Message-----

From: Koch.Kristine@epamail.epa.gov  
To: dawn@bes.ci.portland.or.us  
Sent: 10/3/2007 8:24 AM  
Subject: Kach Machine Works

Dawn - do you have any data from outfall S-2 or sediments directly off outfall S-2 that show TPH or PAH contamination?

Kristine Koch  
Remedial Project Manager  
USEPA, Office of Environmental Cleanup

U. S. Environmental Protection Agency  
Region 10  
1200 Sixth Avenue, Suite 900, M/S ECL-115 Seattle,  
Washington 98101-3140

(206)553-6705  
(206)553-0124 (fax)  
1-800-424-4372 extension 6705 (M-F, 8-4 Pacific Time, only)